



LTPP North Central Regional Office

505 West University Avenue - Champaign, IL 61820-3915 - Tel 800 344-7477 - Fax 217 356-3088 - www nerco com

May 9, 2001

Mr. Jack Springer, HRDI-13 FHWA-LTPP Turner-Fairbank Highway Research Center 6300 Georgetown Pike McLean, Virginia 22101-2296

Re: SPS Construction Report for SPS-8 south of Ozark, Missouri

Dear Mr. Springer,

I have enclosed a copy of the SPS construction report for the SPS-8 near Ozark, Missouri. Reports for the remaining projects in Missouri will be completed in the near future, and sent to you as they are available. Please let me know if you have any comments or questions concerning this report. You may contact me at 217/356-4500.

Sincerely,

Brenda B. Mehnert

ERES Division of ARA, Inc.

Enclosures:


cc: M. Symons (FHWA-COTR)

J. Jiang (LTPP-DATS)

Brenda Bouché Mehnert

Construction Report for Missouri SPS-8

DTFH61-96-C-00013



May 1, 2001





SPS-8 Construction Report Christian County, Missouri Frontage Road West of US 65 (approximately 6 km south of Ozark, Missouri)

Sections 290801, 290802, 290807, and 290808

Federal Highway Administration LTPP Division North Central Region

> Report Prepared By: Brenda B. Mehnert

ERES Consultants
A Division of Applied Research Associates, Inc.
505 West University Ave.
Champaign, Illinois 61820

TABLE OF CONTENTS

1	PROJECT OVERVIEW]
	1.1 EXPERIMENT CELL	
	1.2 PROJECT LOCATION	
	1.3 PROJECT LAYOUT	
	1.4 Traffic Characteristics	
	1.5 LIMITS OF TEST SECTIONS	
	1.6 WEATHER MONITORING	2
	1.7 Traffic Monitoring	
	1.8 PERSONNEL	2
	1.9 Known Deviations from Guidelines	
	1.10 SUMMARY OF KEY CONSTRUCTION EQUIPMENT	
	1.10 SUMMARY OF REY CONSTRUCTION EQUIPMENT	4
_	•	
2	PROJECT DETAILS	
2	PROJECT DETAILS	5
2	PROJECT DETAILS 2.1 DESIGN FEATURES	5
2	PROJECT DETAILS	5
2	PROJECT DETAILS 2.1 DESIGN FEATURES 2.2 MATERIAL SAMPLING AND TESTING 2.3 CONSTRUCTION ACTIVITIES	5
2	PROJECT DETAILS 2.1 DESIGN FEATURES 2.2 MATERIAL SAMPLING AND TESTING 2.3 CONSTRUCTION ACTIVITIES 2.4 SUBGRADE PREPARATION	5
2	PROJECT DETAILS 2.1 DESIGN FEATURES 2.2 MATERIAL SAMPLING AND TESTING 2.3 CONSTRUCTION ACTIVITIES 2.4 SUBGRADE PREPARATION 2.5 PLACEMENT OF BASE LAYER	5
2	PROJECT DETAILS 2.1 DESIGN FEATURES 2.2 MATERIAL SAMPLING AND TESTING 2.3 CONSTRUCTION ACTIVITIES 2.4 SUBGRADE PREPARATION 2.5 PLACEMENT OF BASE LAYER 2.6 ASPHALT PAVING	5
2	PROJECT DETAILS 2.1 DESIGN FEATURES 2.2 MATERIAL SAMPLING AND TESTING 2.3 CONSTRUCTION ACTIVITIES 2.4 SUBGRADE PREPARATION 2.5 PLACEMENT OF BASE LAYER	5

ATTACHMENT A: PROJECT LOCATION

ATTACHMENT B: SITE LAYOUT

ATTACHMENTS

ATTACHMENT C: MATERIAL SAMPLING AND TESTING PLAN

ATTACHMENT D: LAYER DESCRIPTION AND THICKNESS FOR EACH SECTION

ATTACHMENT E: PROJECT DEVIATION REPORT

1 Project Overview

The Strategic Highway Research Program (SHRP) SPS-8 project investigates environmental effects on both rigid and flexible pavements in the absence of heavy loads. This project encompasses both types of structures built on conventional nondrained base materials over three types of subgrade. The factors addressed on the long-term pavement performance of these two types of pavements are:

- Pavement type
- Layer thickness
- Subgrade soil types

The analysis of information developed from this experiment will provide substantially improved data for validation and improvement of the environmental effects models used in the design of rigid and flexible pavements.

Four test sections were constructed for this project, two flexible and two rigid pavement. The flexible pavements consisted of varying base layer thickness and asphalt concrete surface. The rigid pavements had the same base thickness but different PCC surface layer thickness. All the sections were constructed with the same type of base layer and subgrade—crushed stone over a fine-grained subgrade.

This report summarizes the "as-built" pavement layers of the Missouri SPS-8 site that include four SHRP test sections constructed in the late spring 1998 and completed by July 1998. Field tests were performed, and laboratory samples obtained and analyzed, at different stages of construction from each test section. All samples were taken from the southbound lane.

1.1 Experiment Cell

This Missouri SPS-8 experiment is located in the wet-freeze environmental zone and was constructed on a fine-grained subgrade. The existing pavement was removed to accommodate the new pavement structure. The existing pavement was 102 mm of asphalt concrete (AC) placed on 178 mm of crushed rock base placed on a silty sand subgrade following the 1986 AASHTO Structural Design Method.

1.2 Project Location

The Missouri SPS-8 project is located in the southbound lane of the frontage road west of US Highway 65 (US-65) in Christian County, Missouri. This site is approximately 6 km south of Ozark, Missouri, and just west of Selmore, Missouri. Attachment A is a general project location map.

The test site is located on a 3.0 percent downgrade. The horizontal curvature for both sections is tangent. The lanes are 3 m wide and have asphalt concrete shoulders that are 1.2 m wide. The shoulders were constructed with 102 mm of AC on a 203-mm base of crushed stone.

1.3 Project Layout

Attachment B contains the test section layout that summarizes surface thickness and layer descriptions.

1.4 Traffic Characteristics

This two-lane section of frontage road is classified as a local road. Table 1 shows traffic data at the time of construction.

Table 1. Traffic data for Missouri SPS-08.

Annual Average Daily Traffic	50 Vehicles
(two directions)	
Design Period (years)	20

1.5 Limits of Test Sections

Table 2 shows the limits of the test sections at the SPS-8 site. Each test section includes a monitoring section of 152 m and 15 m at each end of the monitoring section to be used as sampling areas.

Table 2. Limits of Missouri SPS-8 test sections.

Test Section	Test S	Section	500-ft Monitoring Section					
#	" Reginning		End Station Beginning Section En					
290801	454+50	460+50	455+00	460+00				
290802	461+00	467+00	461+50	466+50				
290808	467+50	474+00	468+00	473+00				
290807	474+00	480+00	474+50	479+50				

1.6 Weather Monitoring

An automatic weather station (AWS) unit was installed February 2000 inside the Missouri DOT maintenance yard in Ozark. This unit is approximately 6 km from the SPS-8 site.

1.7 Traffic Monitoring

There was no traffic monitoring device installed near this site.

1.8 Personnel

North Central Regional Coordination Office

ERES Consultants, a Division of ARA, Inc.

Tom Wilson

Principal Investigator

505 West University Avenue

Champaign, Illinois 61820 (800) 344-7477

Material Testing

Braun Intertec Corporation
Bruce M. Thorson, PE or David Clauson
LTPP Testing Contractor
P.O. Box 39108
Minneapolis, Minnesota 55439-0108 (612) 941-4151

Jason Blomberg

Research, Development and Technology

Missouri Dept. of Transportation

105 West Capitol Avenue

Jefferson City, MO 65102

(573) 751-2551 and Fax (573) 751-6555

www.modot.state.mo.us

Field Sampling and Testing

Jason Blomberg

Research, Development and Technology

Missouri Dept. of Transportation

105 West Capitol Avenue

Jefferson City, MO 65102 (573) 751-2551 and Fax (573) 751-6555

www.modot.state.mo.us

LTPP Design Review

John Miller

PCS/LAW

A Division of Law Engineering and Environmental Services, Inc.

2104 Indian Creek Court, Suite A

Beltsville, Maryland 20705 (301) 210-4105

State Department of Transportation

Jason Blomberg

Research, Development and Technology

Missouri Dept. of Transportation .

105 West Capitol Avenue

Jefferson City, MO 65102

(573) 751-2551 and Fax (573) 751-6555

www.modot.state.mo.us

Construction Contractor

Leo Journagan
Journagan Construction Co., Inc.
3003 E. Chestnut Expressway
Suite 1200
Springfield, MO 65802

(417) 839-2173

1.9 Known Deviations from Guidelines

Attachment E contains project deviation reports filled out during and after construction.

1.10 Summary of Key Construction Equipment

Subgrade Preparation

• 5.0-ton sheepsfoot

Crushed Stone Preparation

• Single drum vibrator (10.0-ton)

Asphalt Concrete Pavement Placement

- Cedar Rapids (model CR461P) paver
- 10.3-ton steel wheel tandem roller
- 10.1-ton pneumatic rubber-tired roller
- 10.2-ton double drum vibrator @ 1.7mph
- Asphalt concrete drum mix plant

PCC Placement

- Gomaco, Commander 3 paver
- Portland cement concrete mix plant

2 Project Details

Project meetings were held at the District 8 Office Complex in Springfield, Missouri, in August 1996. Representatives from the contractor, sub-contractors, LTPP, and Missouri DOT attended these meetings. Preparation of the subgrade did not begin until March 1998. Construction was completed in July 1998.

2.1 Design Features

Table 3 summarizes the asphalt, concrete, and base layer thickness for each section. Edge drains were not installed in any of the sections.

Test Section Number	Surface Thickness (mm) (Surface)	Material and Thickness (mm) (Crushed Stone Base)	Edge Drains
290801	125 AC	198	No
290802	191 AC	292	No
290808	269 PCC	160	No
290807	193 PCC	160	No

Table 3. Summary of material thickness and edge drains for each section.

2.2 Material Sampling and Testing

Locations of material sampling and field testing for each layer are given in attachment C. LTPP sampling field testing procedures have been developed specifically for the SPS-8 program, and all activities were performed in accordance with these guidelines unless noted in attachment E. Samples for laboratory testing were sent to Braun Intertec and the Missouri Department of Transportation.

2.3 Construction Activities

Removal of the existing pavement for this project began in early 1998. The end sections, 290801 and 290807, were located in fill areas, whereas sections 290802 and 290808 were located in cut and fill areas. Subgrade preparation followed shortly thereafter. Paving operations were completed by mid-July 1998.

2.4 Subgrade Preparation

Subgrade preparation began October 15, 1996, and was completed December 14, 1996. A 5.0-ton sheepsfoot was used for compacting the subgrade. Sections 290801 and 290807 were both in fill sections. Sections 290802 and 290808, located in the center of the project, were in cut and fill sections. Both sections were reconstructed with a typical subgrade lift thickness of 203 mm. The

flexible sections (290801 and 290802) were constructed on a 0.86 percent vertical downgrade. A 0.3 percent vertical downgrade was maintained for the rigid sections (290807 and 290808).

2.5 Placement of Base Layer

Preparation of the unbound base layer began on May 5, 1998, and was completed by June 6, 1998. For sections with a 178-mm base, the first and second lift thicknesses were typically 127 mm and 76 mm, respectively. Section 290802 (with the 279-mm base) had three lifts—127, 76, and 102 mm. The lift thickness represents the thickness before a 10.7-ton single drum vibrator roller was used for compaction.

2.6 Asphalt Paving

Paving operations began June 3, 1998, and completed the next day. Two asphalt concrete mixes are used in these two flexible pavement test sections, the binder course and surface course. The Journagan Drum Mix Plant, located 20 minutes from the site, produced the hot mix asphalt concrete (dense graded) for this site. Placement of the asphalt concrete was performed with a Cedar Rapids, model CR 461P paver with a laydown width of 3 m. There was one longitudinal surface joint located between the lanes. The mean laydown temperature of the asphalt was 135°C, and the air temperature was 27°C. The first layer was allowed to cure for 1 day while the final layer was allowed to cure for approximately 20 days.

The AC binder course was placed before the final AC surface. A minimum compacted thickness of 58 mm for the first lift was maintained for both the AC binder and surface course. For section 290801, the minimum compacted thickness for the second lift was 46 mm, and the minimum compacted thickness for section 290802 first lift was 58 mm. The mean laydown temperature of the asphalt was 136°C, and the air temperature was 27°C.

Typically, for the AC surface layers, breakdown compaction was performed with two passes of an 10.2-ton double drum vibrator. Two passes with a 10.1-ton pneumatic-tired roller were used for the intermediate compaction. Lastly, a 10.3-ton steel-wheel tandem roller made the final two passes.

2.7 Concrete Paving

The paving operation began May 20, 1998, and was completed the same day. The concrete mix plant used was Conco, located 15 miles away, for a haul time of 30 minutes. A Gomaco Commander 3 form paver was used at this site. A 6-m width was paved in one pass. Twelve vibrators were placed 457 mm apart and 102 mm below the surface.


One mix design was used for this project. Type 1 cement was used with two admixtures, airentraining admixture (AASHTO M154) and a retarding admixture (AASHTO M194, Type B). The coarse aggregate was made of 100 percent crushed stone, and the fine aggregate was composed of 100 percent natural sand. The consolidation of materials was attained with vibrating screeds and finishing was completed by hand-troweling. A membrane-curing compound was used, and the surface was textured using a tine.

The surface was profiled June 10, 1998, using a California type Profilograph with a 0.0-in blanking band. No diamond surface grinding was necessary, as the profile index was 27 in/mile.

The average contraction joint spacing was 5 m. Spaced every 4-m were dowels coated with epoxy. These dowels were 457 mm long with a 32-mm diameter. These were installed using preplaced baskets. Transverse joints were sawed to a 51-mm depth and sealed with low-modulus silicone. The longitudinal joint was also sawed along the weakened plane.

Attachment A

Project Location




Attachment B Site Layout

${\bf Attachment} \ {\bf C}$ ${\bf Material} \ {\bf Sampling} \ {\bf and} \ {\bf Testing} \ {\bf Plan}$

0 · 25 '	TRAFFIC	DIRECTION —		0+25
Sample Area 1 B1 G'	T1 + O A1	T2 (PBI) + () A2	T3 + O A3	Sample Area 2
	S1 ⊗	SHOULDER		

SECTIONS 1, 3, 5, 7, 9, 11



SECTIONS 2, 4, 6, 8, 10, 12

LEGEND

■ 82 - Bulk sampling location 2 ft x 2 ft to 1 ft below surface
+ T1 - In - place density test location

○ A1 - Location of Shelby tube/splitspoon sampling to 4 ft. below surface

⊗ S1 - Location of auger probe in shoulder

PB1 - Location of Plate Bearing Test (Rigid Sections Only)

1 in = 25.4 mm

 $1 ext{ ft} = 25.4 ext{ mm}$ $1 ext{ ft} = 0.305 ext{ m}$

Figure C-1. Sampling and testing locations for subgrade






Figure C-2. Sampling and testing locations for base course.



SECTIONS 1, 3, 5



SECTIONS 2, 4, 6


LEGEND

O - 4 inch diameter core of AC surface

+ - Density test location 1 in = 25.4 mm

1 ft = 0.305 m


Figure C-3. Sampling and testing locations for AC surface.



O - 25 TRAFFIC DIRECTION — 0 + 25

Sample Area 3 Sample Area 4

C23 O - 16



SECTIONS 8, 10, 12

LEGEND

○ - 4" Diameter Core of PCC surface

Figure C-4. Sampling and testing locations for PCC surface.

Attachment D Layer Description and Thickness for Each Section

Table D-1. Material codes.

Material Code	Material Description	
111	Fine-Grained Soils: Gravelly Lean Clay	
112	Fine-Grained Soils: Gravelly Fat Clay	
303	Base-Crushed Stone	
700	Asphalt Concrete (AC)	
730	Portland Cement Concrete (PCC)	

Table D-2. Layer description and thickness for each section.

Test Section	Layer Number	Project Layer	Material Code	Average Layer Thickness (mm)
	1	Subgrade	111	N/A
290801	2	Base-Crushed Stone	303	198
SB	3	AC Binder	700	71
	4	AC Surface	700	53
	1	Subgrade	112	N/A
290802	2	Base-Crushed Stone	303	292
SB	3	AC Binder	700	140
	4	AC Surface	700	51
		700 P		
	1	Subgrade	112	N/A
290808	2	Base-Crushed Stone	303	160
SB	3	PCC	730	269
		10 mg		
	1	Subgrade	112	N/A
290807	2	Base-Crushed Stone	303	160
SB	3	PCC	730	193
		444		

Attachment E Project Deviation Reports

LTPP SPS Project Deviation Report Project Summary Sheet	State Code Project Code	0	_8	$\frac{2}{0}$ $\frac{9}{0}$		
Proje	ect Classification Information					
SPS Experiment Number: SPS-8	State or Province: Misson	uri				
LTPP Region:	☐ North Atlantic ☐ North	h Central	Southern	☐ Western		
Climate Zone:	Pry-Freeze Dry-No Freeze	⊠ Wet-Fre	eeze 🔲 V	Wet-No Freeze		
Subgrade Classification:	☐ Fine Grain ☐ Coan	rse Grain	Active ((SPS-8 Only)		
Project Experiment Classification Designation	on (SPS 1, 2, & 8): SPS-8					
Construction Start Date: March 1998	Construction End Date: J	uly 1998				
FHWA Incentive Funds Provided to Agency	for this Project:		\boxtimes	Yes 🗌 No		
	Deviation Summary					
Site Location Deviations:	☐ No Deviations ☐ Minor	Deviations [Signific	ant Deviations		
Construction Deviations:	No Deviations	Deviations [] Significa	ant Deviations		
Data Collect	ion and Processing Status Su	mmary				
Inventory Data (SPS 5,6,7, & 9):	Complete Submission	Incomplete	☐ Data	Not Available		
Materials Data:		Obtained and	Tested [Incomplete		
Construction Data: All Required Data Obtained Incomplete / Missing Data Elements						
Historical Traffic Data:	All Required Historical I Required Estimates			PS 5, 6, 7, & 9)		
Traffic Monitoring Equipment:	WIM Installe	d On-Site	AVC Ins	talled On-Site ment Installed		
Traffic Monitoring: Preferred	Continuous Minimum	Below Min	nimum [Site Related		
Traffic Monitoring Data:	☐ Monitoring Data Submitte	d 🛛 No Mo	nitoring D	ata Submitted		
FWD Measurements:	Pre-construction Tests Perform Post-construction Tests Perform		truction Te	sts Performed		
Profile Measurements: Pre-	construction Tests Performed	Post-cons	truction Te	sts Performed		
Distress Measurements Pre-	construction Tests Performed	Post-cons	truction Te	sts Performed		
Maintenance and Rehab. Data:	Complete Submission	Incomplete	□ Data :	Not Available		
Friction Data:	Complete Submission	Incomplete	□ Data ?	Not Available		
Report Status						
Materials Sampling and Test Plan:	☐ Document Prep	oared 🛛 Fin	al Submitt	ed To FHWA		
Construction Report:	□ Document Preparent □ Document □	pared Fir	nal Submitt	ted To FHWA		
AWS: (SPS 1, 2, & 8)	AWS Installed 🛛 AWS Insta	llation Report	Submitted	to FHWA		
Page 1 of 5 Prepared by	Brenda B. Mehnert		Date _	4-26-2001		

LTPP SPS Project Deviation Report Construction Guidelines Deviation	State Code Project Code	<u>0</u> 8 <u>0</u> <u>9</u>							
Comments Pertain to All Test Sections on Project									
Comments Pertain Only to Section(s): (Specify)									
Construction Guidelines Deviation Comments									
	7								
	- Padrici								

21

Page 2 of 5 Prepared by Brenda B. Mehnert Date 4-26-2001

LTPP SPS Project Deviation Report Other Deviations	State Code Project Code	_0_	8_	<u>2</u> 0	9		
Comments Pertain to All Test Sections on Project							
Comments Pertain Only to Section(s): (Speci	fy)						
Other Deviation Comments							
None known.							
				· .			

Date <u>4-26-2001</u>

Page 3 of 5 Prepared by Brenda B. Mehnert

LTPP SPS Project Deviation Report Site Location Guidelines Deviations	State Code Project Code	0	_8_ 0_ 0_					
Comments Pertain to All Test Sections on Project								
Comments Pertain Only to Section(s): (Specify)								
Site Location Guideline Deviation Comments	Site Location Guideline Deviation Comments							
Page 4 of 5 Prepared by Brenda	B. Mehnert	Da	ate <u>4-26-2001</u>					

LTPP SPS Project Deviation Report Data Collection and Materials Sampling and Testing Deviations	State Code Project Code	_0_	8_	2	9 0			
Comments Pertain to All Test Sections on Project								
Comments Pertain Only to Section(s): (Speci	Comments Pertain Only to Section(s): (Specify)							
Data Collection & Material Sampling and Testing	Deviation Comments							
FWD was not performed before the test section was o	constructed.							
					<u> </u>			
					_			

Date <u>4-26-2001</u>

Page 5 of 5 Prepared by Brenda B. Mehnert

Submitted by



505 West University Avenue Champaign, IL 61820-3915

Phone: (217) 356-4500

Fax: (217) 356-3088

http://www.eresconsultants.com

ERES Project No. 95-075-R1